

	Type	L #	Hits	Search Text	DBs	Time Stamp
10	BRS	L15	96	(polyphase or multiphase) and motor and (back adj emf) and (zero adj crossing\$)	USPAT; EPO; JPO; IBM TDB	2001/02/06 16:30
11	BRS	L17	262	(polyphase or multiphase) and motor and (back adj emf)	USPAT; EPO; JPO; IBM TDB	2001/02/06 16:39
12	BRS	L18	30	17 and position\$ with (error or difference)	USPAT; EPO; JPO; IBM TDB	2001/02/06 16:40
13	BRS	L19	76	(polyphase or multiphase) and motor and (back adj electromotive adj force)	USPAT; EPO; JPO; IBM TDB	2001/02/06 16:42
14	BRS	L20	8	19 and position\$ with (error or difference)	USPAT; EPO; JPO; IBM TDB	2001/02/06 16:42
15	BRS	L21	36	(polyphase or multiphase) and motor and (back adj electromotive adj force) and (zero adj crossing\$)	USPAT; EPO; JPO; IBM TDB	2001/02/06 16:43

2/2